

(E0133/17 NOTAMC E0079/17
Q)EDGG/QOBCN/IV/B/A/000/999/4908N00835E005
A)EDXX B)1701121158
E)BRUCHSAL FUERST-STIRUM-KLINIK
HELIPORT REOPENED.)

(E0134/17 NOTAMN
Q)EDGG/QFPXX/IV/B/A/000/999/4908N00835E005
A)EDXX B)1701121201 C)1704121201 EST
E)BRUCHSAL FUERST-STIRUM-KLINIK
HELICOPTER LANDING SITE REOPENED FOR HEMS-OPERATION.
DUE TO CONSTRUCTION WORKS AND OBSTACLES ALL AFFECTED FLIGHT CREW
OPERATING INTO AND FROM BRUCHSAL, FUERST-STIRNUM-KLINIK ARE OBLIGED
TO CHECK THE AVIATION SUPERVISION ORDER ISSUED BY THE CAA-OFFICE
STUTTGART AVAILABLE UNDER:
HTTP://WWW.FUERST-STIRUM-KLINIK.DE/)

(E0132/17 NOTAMC E2649/16
Q)EDGG/QFPCN/IV/B/A/000/999/4908N00835E005
A)EDXX B)1701121157
E)BRUCHSAL FUERST-STIRUM-KLINIK
SPECIAL HELICOPTER LANDING SITE KREISKRANKENHAUS BRUCHSAL REOPENED.)